


Fig. 1






Fig. 3




Fig. 4






Fig. 5

6/37









Fig. 7







Fig. 9

10/37







Fig. 11

12/37








Fig. 13


14/37





(a) Before Adhesion of Paper Dust (b) After Adhesion of Paper Dust

Fig. 15






Fig. 17





Fig. 18

18/37






Fig. 20




Fig. 2




Fig. 22





Fig. 2.



F1g. 24




Fig. 25




Fig. 26




Fig. 27

27/37

0

 Table 1 (Example of Judgment of Cause of Ejection Failure)

 Normal Ejection
 0
 0
 0

0 0

Adhesion of Paper Dust Intrusion of Air Bubble

Drying




Fig. 29




Fig. 30




Fig. 31




Fig. 32

32/37

 Table 2 (Example until 1/2 Cycle)


 Normal Ejection
 0 0 0
 0 0 0

 Drying
 0 1 1
 0 1 1

 Adhesion of Paper Dust
 0 1 0
 0 1 0

 Intrusion of Air Bubble
 1 0 0
 1 0 0

33/37








Fig. 35

35/37



36/37



37/37

